

FIRE/LIFE SAFETY INSPECTION REPORT

ADULT/JUVENILE DETENTION FACILITIES

Facility:

43-50-45-0002-000-040-L
 STANISLAUS CO JUVENILE HALL
 2215 BLUE GUM AVE
 MODESTO CA 95351

FACILITY TYPE: (check one)
 Adult max/med security
 Adult minimum security
 Juvenile max/med security
 Juvenile minimum security
 Holding Cell(s) only

An inspection of this facility was conducted per the mandate of Section 13146.1, California Health and Safety Code, and applicable requirements of Titles 19 and 24, California Code of Regulations. (Check appropriate box)

- No deficiencies affecting fire/life safety were noted. Fire clearance is granted.
- Minor deficiencies affecting fire/life safety were noted and are pending correction. Fire clearance granted
- Fire clearance is withheld pending correction of deficiencies. (List of deficiencies is attached).
- Prisoners are no longer detained at this facility.

The authority conducting the inspection shall submit copies of this report to the appropriate bodies listed below. Where fire/life safety deficiencies are noted, a list of the deficiencies must accompany this report.

- Office of the State Fire Marshal
 Fire & Life Safety Division
 P.O. Box 944246
 Sacramento, CA 94244-2460
 FAX: (916) 324-3784
- Board of Corrections
 Facilities Standards & Operations Division
 600 Bercut Drive
 Sacramento, CA 95814
 FAX: (916) 327-3317
- Official in Charge of the Facility
- Local Governing Body (i.e., Board of Supervisors, City Council, etc.)

BOARD OF SUPERVISORS
 2010 SEP 13 12:00

Date of Inspection: 08/31/2010 Inspected by: MIKE GAIN

Fire Authority: MODESTO FIRE DEPARTMENT

Facility Representative: NATASCHA ROOF

ADULT/JUVENILE DETENTION FACILITY INSPECTION GUIDE

CORRESPONDENCE NO. 1 Page 2 of 3

The following is to be used only as a guide and is not intended to include all applicable codes and requirements.

		Yes	No	N/A
A. CONSTRUCTION				
1.	Building construction type and fire resistive rating conform throughout and are maintained in good repair. (19 CCR 3.24; CBC 308.2.2.2; CBC 324A.1; CBC 324A.2; CBC Table 6-A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2.	Proper interior ceiling and floor finish ratings are provided. (CBC 324A.4, CBC Table 8B)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3.	Vertical shaft enclosures are in good repair and fire assemblies at openings are properly maintained. (CBC 711, Table 6A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
B. EXITS				
4.	Proper corridor construction and opening protection are provided and maintained. Dead-end corridors do not exceed 20 feet in length. (CBC 1004 through 1006). Exit balconies do not exceed 50 feet. (CBC 332A.4)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5.	All means of egress are unobstructed and free of storage. (19 CCR 3.11)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.	Means of egress and exit signs are installed, illuminated and maintained. (CBC 1003.2.8.2 through 1003.2.9.2; CBC 331A.5)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7.	Corridors are not used as part of the air distribution system. (CMC 602.1)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
8.	Supervisory personnel are continually on duty and effective provisions are made to remove occupants in case of fire or other emergency. (Penal Code 6030[c]; CBC 1003.3.1.8 exception 3)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
C. MECHANICAL/ELECTRICAL				
9.	Fire and smoke dampers and similar devices are adequate, properly installed, maintained and tested. (CMC 606.1 & 2; CBC 713.10, 713.11)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.	All heating, cooling and ventilation equipment is maintained satisfactorily. There are no visible defects. (CMC 109.2; 19 CCR 3.02)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11.	Electrical wiring, fixtures and appliances are properly installed and operated. (19 CCR 3.01; CBC 3.24)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.	Emergency power is provided for minimal lighting and fire/life safety systems. (CBC 1003.2.9; CBC 328A)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
D. HOUSEKEEPING				
13.	Kitchen hoods, vents, ducts and filters are installed, adequate, are maintained in proper condition and are free of grease. (19 CCR 3.19, 3.24; CMC 501 through 510)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14.	All areas are free of unacceptable amounts of storage. (19 CCR 3.19)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
E. FIRE EXTINGUISHING/FIRE ALARM				
15.	All portable fire extinguishers, automatic fire sprinkler systems, wet and dry standpipe systems are installed and maintained properly. (19 CCR 3.24; 19 CCR 3.29; 3.29A; NFPA 13)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.	Manual and automatic fire alarm systems, when installed, shall be properly installed and maintained. (19 CCR 3.24; CBC 330A; NFPA 72)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17.	The automatic fire alarm system is properly maintained. (19 CCR 3.24)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
F. TRAINING/PREPLANNING				
18.	At least one person is on duty who meets the training standards established for general fire and life safety relating specifically to the facility. (Penal Code 6030[c])	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19.	Fire suppression preplanning inspections are conducted by the local fire authority at least every two years. (Penal Code 6031.1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Code references above are from the most recent SFM adopted codes. Note that code references for the CBC may be different for facilities constructed prior to the revision of this form.

Where any deficiency is identified, please provide specific information regarding the deficiency type and location (e.g., the fire alarm in Building C indicated a trouble alarm and must be repaired.)

ANNUAL INSPECTION DISTRIBUTION FOR JUVENILE HALL

STANISLAUS COUNTY JUVENILE HALL
SUPERINTENDENT
2215 BLUE GUM AVE
MODESTO CA 95351

STANISLAUS COUNTY BOARD OF SUPERVISORS ✓
CHAIR PERSON
1010 10TH STREET STE 6500
MODESTO CA 95354

OFFICE OF THE STATE FIRE MARSHAL
FIRE & LIFE SAFETY DIVISION
P.O. BOX 944246
SACRAMENTO CA 94244-2460

BOARD OF CORRECTIONS
FACILITIES STANDARDS & OPERATIONS DIVISION
600 BERGUT DRIVE
SACRAMENTO CA 95814